

2 Northpoint, San Francisco

Photos from 2/12/20 – Structural Upgrades



Open Office with each column capital installed.



Open Office with each column capital installed.



Coordination of column capitals, walls and utility systems.



Coordination of column capitals and utility systems.

2 Northpoint, San Francisco

Photos from 2/12/20 – Structural Upgrades



Installing dowels and rebar in existing building shear wall.



Supplemental metal column instead of column capital.



Existing shear wall prepared to accept new concrete shear wall.



3rd Floor Gathering Area progress.